		Approved For Release 2002/08/08 GIAFRDP82-00457R006500240005-6	V M V dox
		CLASSIFICATION STORM / CONTROL/US OFFICIALS OUTLY	25×
		(Soviet Zone) REPORT NO.	
TOPIC Witt	stock	Airfield	entrement beschools were
A MARIA OR SPRINGER STANDA SERVICE CONTROL OF THE ANALYSIS OF	annulagende dalphal		To a second designate of the second design of the s
		OLOW PLACE OBTAINED	25X
	TENT_	mid-September to 11 October 1350	
5X1 DATE OBTAINI	ED.	DATE PREPARED_9 November 1950	25X
REFERENCES			
PAGES3	u 2000 bak di wasan ishi wasan milik	ENCLOSURES (NO. & TYPE) 1 - detch on ditto	
		TURN TO LIA	
tiges special extensionality as consequent or standard, equipment property	E 94	LIBRARY	ayaan aa aga ayada d aaba,PAGALa t oo sa
METEROACTION THAT I SULLE COLOR CLASS PROPERTY OF THE		LILL -	gih ang pang yang Tanipat palibusan repincin nara risning s
0EV4	·		r a fragadistration of the control o
25X1 SOURCE	Γ		
X1	1.	Only 10 biplanes were stationed at the Wittstock (N 54/V 11) airfield in mid-September 1950. (1) The field was not suitable	
		for night flying. The barracks were occupied by about 250 air	
		force personnel. Some temporary buildings were occupied by an air force headquarters. (2) A very large number of officers	
	•	ranking from captain upward were at the field and in the town.	
			25X
	_	to di to 200 beauth affice of the Boundar Bond Firm	
	2.	The Waren (N 54/U 35) branch office of the Baumion Nord Firm had constructed a concrete east-west runway, 2,000 meters long	
		and 60 neters wide. This runway which was being extended toward	
		the east by 250 meters was scheduled to be completed by 1 October 1950. (3) Rost of the 600 laborers previously employed for con-	
		struction work at the field had already left. For the construction	
		of the runway and the taxiways the earth had been excavated to a	
		depth of 80 cm and 10 cm, respectively. The excavations were filled with gravel, which was covered by a concrete layer 15 cm	
		thick. The concrete was mixed in a ratio of four units of gravel, 2 units of crushed stones and one unit of coment. (4)	
	3.	Seven jet fighters with swept-back wings were counted at the Wittstock airfield between noon and 1 p.m. on 5 October 1950.	
		An estimated 13 more aircraft of the same or a similar type were	
		noticed south of the runway. (1) and numerous Soviet air force officers and Elivere seen on the road from the	25X
		field.	
	4.	A local resident said that the construction work at the field	
	40	would be completed by late October 1950. Excavating and grading	
		work was being done at the northern edge of the field. Five wooden huts of the Jaren branch office of Rauunion Nord were seen at the	
		western edge of the field. The runway, which measured about 2,000x	
•		55 meters, runs parallel to Daber Canal and 700 to 800 meters south of it. The western end of the runway was enlarged slightly	
		Boroment Ro. 004	
Lo		CLASSIFICATION SECRET /CONTROL/US COPECHALS ONLY	
••• ••		Berlees Coll	et als de geleinge bereigtigt de filige de filie egenegyte freig
		CONFIDENTIAL Auth.: No 32] 051/
		Baio: 13 July 78	25X

Approved For Release 2002/08/08 : CIA-RDP82-00457R006500240005-6

25X1

*		SECRUT/CONTROL/US OFFICIALS ONLY				
		, ²				
		to the north and south. The eastern end of the runway could not be seen. A high-tension line suspended from wooden poles about 6 meters high led from Altdaber (N 54/U 12) toward the southeast as far as a point 50 meters north of the runway. From there masts without wires and lamps set up parallel to the runway, toward the east.				
25X1	5.	No aircraft were observed at the field on 7 October 1950. It was noticed that planes were in the hangers. An observation tower, 2.50 m high, with view ports on all sides and erected on the top of a building about 12 meters high, was seen in altdaber.				
		5. Employees of construction firms said that the runway at "littstock airfield was completed to a length of 1,000 meters by mid-September 1950. Only clearing work was still being done and this was to be completed by 1 November 1950.				
	7.	Air force personnel stationed at the field said that jet aircraft from Rochlin (N 54/U 33) were expected to arrive. (5)				
	8,	On 19 September 1950 eight jet aircraft with swept-back wings and rudder assemblies set high landed at the field, taking off again after one hour.				
	9.	A radar set was on Rockstaedt Hill, south of the field, on 2 October 1950. (6)				
	10.	according to local residents, three houses of Altdabor, located in the northwestern corner of the field, were to be evacuated and torn down since they were an obstacle to flying.				
	11.	The following trucks were observed at the field during the period from 16 September to 11 October 1950:				
25X1						
		(7)				
25X1	12.					
	13.	The administrative officer of the hospital was Junior Lieutenant Vinogradov (fnu), Rajor Zaburumov (fnu), surgeon; Major Namochodshayev (fnu), dormatologist; ajor Lokvinenko (fnu), general practitioner; Captain Kremishov (fnu), dentist; and Junior Lieutenant Rendorenko (fnu) pharmacist, were medical officers and assigned to the hospital. (9)				

SECRET/CONTROL/US OFFICIALS ONLY